

Info Sheet for...

Easy-Glide & Easy Go



Fast wax for glide. 60ml.
Universal -10..+10C / +14..+50F

1. Spread a thin layer over the glide zone.
 2. Let dry for 3 minutes.
 3. Brush with a nylon brush.
- Good to go.

**No scraping
needed!**

Easy-Glide protects your skis.
Unlike similar products on the market,
Easy-Glide contains no solvents that make
your ski base hard and dry.
Protect the bottle from freezing.

Modern fast waxes make it easy to wax.
Apply and ski -- Can it be easier?

Fast wax for kick. Two Choices.
Easy-Go Minus -1..-15C / 30..5F
Easy-Go Plus +1..+10C / 34..50F

1. Apply
2. Let Dry.
3. Ski



**No corking
needed!**



Official Supplier to numerous National Teams in
Sweden, Norway, Finland, Russia and Canada.



For more information contact Skigo or visit your local retailer.